BUILDING SAFETY CERTIFICATE

This is to certify that the building of Shri. A. B. Patil English School, situated at Dhamani Kolhapur Road, Sangli - 416416 is inspected by me and Sectional Engineer P.W. Section, Sangli

The G+1 school building is in order for educational purpose under normal circumstances based on visual inspection by this office, However the safety of building with respect to R.C.C. design from the consultant appointed by the school management.

The Compliance for the following points should be made -

- 1) Ramp should be constructed for disabled persons
- 2) Railing should be provided for the ground floor corridor.
- 3) The height of railing at first floor shall be sufficient in order to avoid untoward incidents.
- 4) The electrical switch panels should be energed with wooden/steel box & these should be accessible by trained person only.
- 5) The electrical wiring should be hidden or covered.

Counter Signed

Assistant Executive Engineer Class- 1

P.W.Sub-Division, Sangli

No. DB/Building/ /2021

Office of the Executive Engineer

P.W. Division, Mirai

Date:- 25/02/2021

A.B.Paul English School Samo?

PRINCIPA

Shri. A. B. Patil English School, Sangil

(CBSE/AFFL /1130484)

Shri. A. B. Patil English School, Sangle (CBSE/AFFLI./1130484)

ri A.B.Patil English School,Sangli.